Second Report on the
Investigation of Remedial Measures for
Combating Accelerated Oxidation Induced by
Vanadium Contamination

Research and Development Report 040088
NSM-013-120

4 September 1956

Ву

W. J. Greenert and L. G. Richards

HARD COPY \$. 1.00
MICROFICHE \$. 0.30



ARCHIVE COPY

CLEARINGHOUSE FOR FEDERAL SCIENTIFIC AND TECHNICAL INFORMATION CFSTI DOCUMENT MANAGEMENT BRANCH 410.11

LIMITATIONS IN REPRODUCTION QUALITY

ACCES	S10	N # AD 607150
1		WE REGRET THAT LEGIBILITY OF THIS DOCUMENT IS IN PART UNSATISFACTORY. REPRODUCTION HAS BEEN MADE FROM BEST AVAILABLE COPY.
		A PORTION OF THE ORIGINAL DOCUMENT CONTAINS FINE DETAIL WHICH MAY MAKE READING OF PHOTOCOPY DIFFICULT.
		THE ORIGINAL DOCUMENT CONTAINS COLOR, BUT DISTRIBUTION COPIES ARE AVAILABLE IN BLACK—AND—WHITE REPRODUCTION ONLY.
		THE INITIAL DISTRIBUTION COPIES CONTAIN COLOR WHICH WILL BE SHOWN IN BLACK-AND-WHITE WHEN IT IS NECESSARY TO REPRINT.
		LIMITED SUPPLY ON HAND: WHEN EXHAUSTED, DOCUMENT WILL Be available in Microfiche Only.
	5 .	LIMITED SUPPLY ON HAND: WHEN EXHAUSTED DOCUMENT WILL NOT BE AVAILABLE.
	1.	DOCUMENT IS AVAILABLE IN MICROFICHE ONLY.
	B .	DOCUMENT AVAILABLE ON LOAN FROM CFSTI (TT DOCUMENTS ONLY).
	9.	
T\$! _ !	107_	PROCESSOR: each

TSL-107-10/64

U. S. NAVAL ENGINEERING EXPERIMENT STATION

Annapolis, Maryland

Second Report on the
Investigation of Remedial Measures for
Combating Accelerated Oxidation Induced by
Vanadium Contamination

Research and Development Report 040088 NSM-013-120

4 September 1956

Ву

W. J. Greenert and L. G. Richards Mechanical Metallurgy Branch

Approved by

Forwarded by

W. C. Stewart
Superintendent
Metallurgical Laboratory

W. W. Brown Captain, USN Director

ABSTRACT

The oxidation characteristics of vanadium contaminated surfaces as affected by various treatments are described. It was found that coatings of the alkaline earth oxides substantially reduce the corrosion of 25-20 chromium-nickel steel. Treatments are described in sufficient detail to permit the development of procedures for applying the remedial substance to an actual boiler.

irded by

Brown in, USN for

ADMINISTRATIVE INFORMATION

This investigation was authorized by Bureau of Ships letter \$51/1-1 (343) serial 343-96 of 21 February 1955.





TABLE OF CONTENTS

t.e	r	

ABSTRACT ADMINISTRATIVE INFORMATION REPORT OF INVESTIGATION Introduction Method of Test Results of Test Discussion Conclusions Recommendation References	
ADMINISTRATIVE INFORMATION REPORT OF INVESTIGATION Introduction Method of Test Results of Test Discussion Conclusions Recommendation	
REPORT OF INVESTIGATION Introduction Method of Test Results of Test Discussion Conclusions Recommendation	ii
Introduction Method of Test Results of Test Discussion Conclusions Recommendation	ili
Method of Test Results of Test Discussion Conclusions Recommendation	
Results of Test Discussion Conclusions Recommendation	1
Discussion Conclusions Recommendation	1
Conclusions Recommendation	2
Recommendation	10
	15
References	15
1.0.0.0	15
ILLUSTRATIONS	
Figure 1 - Chart Showing Effectiveness of Remedial	
Substances on Laboratory Contactinated	
Specimens	3
Figure 2 - Graph Showing Effect of CaO Treatment During	
Long Term Oxidation	4
Figure 3 - Photograph of Accelerated Oxidation Test	
Specimens	5
Figure 4 - Constitution Diagram of V2O5 - CaO System	8
Figures 5-9 - Graphs Showing Oxidation Characteristics of	
Various Surfaces Treated by Remedial	
Measures . 11-	13
LIST OF TABLES	
Table 1 - Results of Oxygen Consumption Tests of	
Remedial Coatings	Ĵ
Table 2 - Solubility of Vanadium Slags in Water	8
Table 3 - Results of Water Washing Contaminated Surfaces	10

REPORT OF INVESTIGATION

INTRODUCTION

Fireside metal supports and similar parts are subject to a rapid and catastrophic deterioration when contaminated with vanadium oxides. Source of vanadium is residuum fuel derived from crudes of certain areas of the world. The seriousness of this problem is increasing steadily because of a continuing trend toward higher operating temperatures in fuel burning equipment. If remedial measures are not found, economies inherent in the utilization of fuels from various sources together with common bunkering may be curtailed. As a complete solution to this problem is not at hand, it would seem expedient to consider available means for extending the service life of equipment under prevailing contaminating conditions.

Findings from an initial survey of remedial surface treatments to combat accelerated oxidation of fireside surfaces were presented in reference (a). These treatments were aimed at reducing the corrosion of surfaces which had been contaminated under the combustion of vanadium-bearing fuel oil. Of the treatments studied, those relying on alkaline earth oxides proved most effective.

Additional findings in the investigation of remedial treatments including the long-term effectiveness of calcium oxide are presented in this report. The relative effectiveness of a number of other substances is also shown. Other results include the effect of surface treatments on the water solution and removal of vanadium-bearing slags and scales.

METHOD OF TEST

The effectiveness of various surface treatments in reducing accelerated oxidation of contaminated 25-20 Cr-Ni steel was determined by the oxygen consumption test. A description of this test is contained in reference (a). Briefly, the test measures the volume of oxygen consumed by an oxidizing surface. The tests reported herein were conducted at 1600°F and, except where indicated as otherwise, had a duration of three hours.

RESULTS OF TEST

Effect of Certain Metallic Oxides on the Oxygen Consumption of Laboratory Contaminated Specimens

Various oxides were applied to specimens of 25-20 Cr-Ni steel. These specimens were precontaminated in a pseudo-ash consisting of 37% V₂O₅, 49% NaVO₃, and 14% Na₂SO₄. The specimens were contaminated by immersing them in the ash for two hours at 1600°F. This treatment developed a surface which, when subsequently tested, had a total oxygen consumption of approximately 100 cc/sq in for three hours. This level of consumption is equivalent to that found for the most severely service contaminated tube support plate tested to date.

Thick water slurries of the following metallic oxides were applied to precontaminated specimens. Two coats were brushed on to the surface and dried for five minutes at 1400 °F. Only one oxide was applied to a particular specimen.

Cupric Oxide
Barium Monoxide
Cadmium Oxide
Titanium Dioxide

Chromium Trioxide
Manganese Dioxide
Nickelic Oxide
Cobaltic Oxide

The oxygen consumption of coated and uncoated specimens were determined. Results of these tests are tabulated in Table 1. The effectiveness of the various oxides in arresting accelerated oxidation is indicated in Figure 1. Included in this figure are data on the alkaline earth oxides previously reported on.

It is apparent that of the substances tested only cadmium oxide approaches the effectiveness of alkaline earth oxides in remedial action. Surprisingly, barium monoxide was not nearly as effective as the peroxide or hydroxide. Poorest showing was made by chromium trioxide which greatly intensified the corrosive action.

In order to more firmly establish the oxide application as a sound remedy, the long term effect of a calcium oxide coating was examined. Oxidation characteristics of coated and uncoated specimens were determined over a period of 165 hours. The remedy consisted only of the initial application of calcium oxide. The results are shown in Figure 2. It is apparent that this remedy is highly effective even for extended periods of time. A photograph of the specimens after test is shown in Figure 3. The protection afforded is striking as the untreated

Table 1
Results of Oxygen Consumption Tests of Remedial Coatings
Coatings Applied to Laboratory Contaminated Specimens

	Tot	al Oxyg	gen	
	Consumed			% Red. of
	Per Sq In - CC			Accelerated
Remedial Coating	l Hr	2 Hr	3 Hr	Oxidation
None ,	44	94	135	-
Cadmium oxide slurry, CdO cp	8	16	26	81
Nickelic oxide slurry, Ni ₃ O ₄	22	45	64	53
Barium oxide slurry, BaO purified	20	49	75	44
Cobaltic oxide slurry, Co2O3	26	60	86	36
Cupric oxide slurry, CuO	27	60	91	33
Manganese dioxide slurry, MnO2	45	85	122	10
Titanium dioxide, TiO2	46	93	139	-2
Chromium trioxide, GrO3	87	169	242	-79




Figure 1

Effectiveness of Remedial Substances in Arresting
Accelerated Oxidation of Laboratory Contaminated Specimens

f ed ı

ARESTING ---

- INTENSIFYING

· %

Test Temperature - 1600°F Specimen Material - 25-20 Cr-Ni Steel





Figure 2
Oxygen Consumption of Laboratory Contaminated Specimens
Showing Effect of CaO Remedial Treatment During
Long Term Oxidation Period

Specimen Material - 25-20 Cr-Ni Steel



A = Contaminating scale removed - untested.

B = Contaminating scale intact - untested.

C = Remedied with CaO coating - tested 165 hours at 1600°F.

D = Unremedied - tested 165 hours at 1600 °F.

Figure 3

Accelerated Oxidation Test Specimens
Showing Effect of CaO Remedy

specimen was largely consumed, whereas the coated specimen showed comparatively little damage. Of particular interest, is the persistent high rate corrosion of the uncoated specimen. As no replenishment of surface contaminant was made, the accelerant appears to be neither consumed or diluted during oxidation.

Effect of Certain Metallic Oxides on the Water Solubility of Slags

The effect of alkaline earth oxide applications on water solubilities of vanadium slags was studied. Freudo slags consisting of V2O5 with various proportions of CaO, MgO, and BaO were prepared and their solubilities determined. A sample of service slag was treated with CaO and likewise tested.

Results of slag solubility tests are shown in Table 2. Additions of CaO and especially MgO to vanadium pentoxide greatly increased the water solubility of the resulting slag. On the other hand the additions of BaO has little effect. Apparently an optimum quantity for maximum solubility exists for both CaO and MgO. This appears to be between 8 to 20% for CaO and about 18% for MgO.

Included in Table 2 is the service slag from the USS CARPELLOTTI. The solubility increase affected by CaO is not so pronounced. However, the slag itself contained 11% total of calcium and magnesium (see reference (d)). Thus, on heating to 1600 °F, considerable solubility was induced by substances already in the slag.

The phase diagram of the V2O5 - CaO system, as depicted by Morosov in reference (b), is presented in Figure 4. Calcium vanadates are shown at 23, 38, and 48% CaO. These correspond to mol ratios of 1:1, 1 2, and 1:3 of V2O5 CaO, respectively. A eutectic at 8% CaO is also shown. Mellor, in reference (c), states that various V2O5 CaO x H2O compounds are water soluble. Deposits of these compounds are found in nature.

The results presented in Table 2 show that slags formed from 1:2 and 1:3 mixtures of V2O5. GaO and V2O5 MgO were much less water soluble than the 1-3 mixture slags. Also, the water solubility of the succetic slag was quite low:

Table 2 .
Solubility of Vanadium Slags in Water

		Temp of	Observed	
		Slag	Melting	
	Mol	Formation	Point	%
Slag Constituents	Ratio	•F	*F	Soluble
V2O5 cp		1600	-	4
V ₂ O ₅ + 8% CaO		1200	1150	9.5
V205 + 8% CaO		1600	1150	12
V205 + 20% CaO*		1600		48
V2O5 + 23% CaO	i-1	1600		37
V2O5 + 38% CaO	1-2	1900	1800	15
V2O5 + 48% CaO	1-3	2300	2200	1
V2O5 + 18% MgO	1-1	1600	1430	94
V2O5 + 18% MgO	1-1	1600]	88
V2O5 + 33% MgO	1-2	2050	1950	61
V2O5 + 43% MgO	1-3	2200	2950	21
V2O5 + 20% BaO		1600	1050	10
V2O5 + 46% BaO	1-1	1600	1375	2
Service slag from USS]
CARPELLOTTI, as removed		-		41
Same		1600		72
Same + 9. 9% CaO	1-1+	1600]	84

* 1-1 nol ratio based on amount of equivalent V205 in slag




Figure 4

Constitution Diagram of CaO-V2O5 System From Kelerence (c)

Effect of Water Washing on the Removal of Scale from Laboratory and Service Contaminated Specimens

The amount of scale removed in washing vanadium contaminated surfaces, represented by laboratory and service specimens, was investigated. The laboratory specimens were precontaminated as described earlier. The service specimens were removed from three failed superheater tube support plates. These plates exhibited vastly different surface conditions and probably represent variations in service operation. The plate from the USS CARPELLOTTI was heavily slagged and had a heavy, glazed black underlying scale. Very little metal wastage was apparent. The USS MALOY plate exhibited a tight, thin reddish scale over a smooth metal surface. No slag was present on the surface but considerable thinning of plate had occurred. The USS LEE plate exhibited a rough, porous, lumpy, brown scale over a roughly contoured metal surface. No slag was adhering to the surface and moderate thinning had occurred.

The above specimens, as-contaminated, annealed, and coated and annealed conditions, were given two 45-minute immersions in 190°F water. No mechanical cleaning action was done. The extent of scale removal was determined by weight loss and visual observation.

Results of the tests are shown in Table 3. The prewashing treatments promoted spalling and handling losses, which preclude weight loss comparison between the various specimens. Indications are, however, that MgO induces greater scale removal than does CaO. The effect of such treatments on accelerated oxidation of 25-20 Cr-Ni steel is shown in the next section.

Effect of Remedial Treatments on the Oxygen Consumption of Laboratory and Service Contaminated Specimens

Oxidation characteristics of contaminated 25-20 Cr-Ni steel surfaces treated by various remedial methods were determined. Prior to remedial treatment, the laboratory specimens were contaminated with sulfur bearing or nonsulfur bearing pseudo-vanadium stags. The service specimens were as described in the preceding section. The following treatments were applied before the oxygen consumption test:

- 1. Treatment A Water wash.
- 2. Treatment B Annea! at 1600 F and water wash.

Table 3

Results of Water Washing Contaminated Surfaces
(Specimens Immersed in 190°F Water)

	l'en ed	v Trestreat	Weight Lose o	
		Treate e 1	Water	Ŧ 4
ļ		Prizero	Wast	Observed Surface Change
Specimen	C-attog	Washing.	gr in	Die to Water Wash
	None	Mone	6 103	Some spailing at edges
	None	1600 F nes:	0 260	Ne 'er enge
	Can	le 'F inneal	0 243	Smooth agot surface
Laporatory*	CaO	ltt 'F ammeal	9. 037	So corring of earlier
	CaO	165hr 1 1:00 F	0, 163	Sn potring it karlace
	MgO	1600 F anneal	0 177	In reased porcesity, emouthing of surface
	None	lione	0 6 50	Color change, gray to brown
Tube support plate from	None	1600 F anneal		Increased porosity
USS CARPELLOTTI	CaO	1600 F annea!	0.055	Scale removed from large areas
	MgQ	1600 °F inneal	0 046	Scale removed from large areas
	None	None	0.002	Co.or ct inge, red to black
Tube support plate from	None	Jr00 F annea'	0.010	No change
"SS MAL OY	CaC	tt00 F amen'	0 014	Smoothing of surface
	MgO	1000 Fannea	0 022	Linerensed porosit.
Taba a sa	None	None.	0.14	No apparent change
Tube semport plateffrom l	None	1600 F. annea!	0 972	fireressed porosity - crumbly
Cos CEE	Can	1670 F anney!	0 135	Smoother of surface

. 25 29 Cr-Ni steel prescaled in sulfur bearing tanadism, slig

3. Treatment C - Calcium oxide coat.

4. Treatment D - Calcium oxide coat, anneal at 1600 °F, and water wash.

Figures 5, to 9, inclusive, show oxidation curves for the above treatments and specimens. Examination of these curves reveals that Treatment D is generally more effective than Treatment C. Both treatments substantially reduce the corrosion from nonsulfated, high intensity, vanadium slags as well as from sulfated, low intensity, vanadium slags. The same treatments were also substantially effective when applied to the service contaminated surfaces.

DISCUSSION

Details of the various remedial methods investigated are discussed in appropriate sections under Results of Tests.

Specimen Material - 25-20 Cr-Ni Steel Slag - 37% V₂O₅ - 49% NaVO₃ - 14% Na₂SO₄

Batch No. 1 - Slag - - - Batch No. 2 - Slag - - -





Figure 5

Effect of Remedial Treatments on
Surfaces Contaminated in Low Intensity Sulfated Slags



Specimen - 25-20 Cr-Ni Steel Slag - 63% Na VO3 - 37% V2O5

Figure 6

Effect of Remedial Treatments on
Surfaces Contaminated in High Intensity Nonsulfated Slag




Figure 7
Effect of Remedial Treatments on USS CARPELLOTTI Tube Plate




Figure 8
Effect of Remedial Treatments on USS MALOY Tube Plate




Figure 9
Effect of Remedial Treatments on USS LEE Tabe Plate

Results of these laboratory tests indicate that the accelerated exidation of fireside surfaces induced by vanadium slags can be controlled by the application of certain substances to the contaminated surfaces. Substantial reductions in corrosion intensities of pseudoslags and service induced fireside scales occurred when alkaline earth oxides were applied. Calcium oxide and magnesium oxide not only inhibited corrosion but conditioned the slag and scale for easier removal. Of the two, calcium oxide performed more consistently in the tests. Also, test data presented in reference (a) showed that hydrated lime was as effective as chemically pure calcium oxide.

Suitable techniques for the application of these remedial substances to boilers in service would have to be developed. It would seem that this is a task for a boiler operating agency. The test data merely point out features that should be considered when setting up a procedure. Two treatments are visualized one for use when the boiler is steaming or in stand-by status; the other for when the boiler is on down time as during repair or overhaul. The sensitive fireside surfaces should be coated periodically with an alkaline earth oxide or mixture of oxides. This assumes that a procedure for applying the coating during steaming . and stand by can be worked out. The frequency of application and the amount of oxide required will be determined by the following factors. (a) vanadium content of fuel ash. (b) amount of fuel fired, and (c) visual observation of slag deposition. For example, firing an oil high in equivalent V2O5 which exhibits a hig' deposition rate. would require more frequent and heavier application than for an oil low in V2O5 with an equal deposition rate, or one high in V2O5 with a low deposition rate. In reference (e) it was shown that the amount of V2O5 occurring in fireside deposits is about 40% of that found by oil ash analysis. Calcium oxide in an amount equal to 23% of equivalent V2O5 in the fireside deposit is needed for stoichiometric balance.

These vanadium bearing slags when coated with calcium or magnesium oxides and heated for a time form water soluble compounds. These compounds are formed within the temperature range 1150° to 1450°F. Tests have indicated that two hours at this temperature is sufficient to effect this change. It should be possible to remove the loosely adherent portions with sootblowers or air lances. Water washing should be effective for removing a considerable portion of the corrosive substance from the remanent slag. Prior to firing again, susceptible surfaces should be coated with the oxide material.

CONCLUSIONS

The following conclusions are derived from the foregoing information together with data presented in reference (a).

Ac lelerated oxidation of 25-20 chromium-nickel steel surfaces contaminated with vanadium can be reduced substantially by the application of alkaline earth oxides.

Reduced corrosion rates resulting from alkaline earth additions are maintained when there is no further contamination.

Results of the long-term test (165 hours) have indicated that the active contaminant of a corroding slag system is neither consumed nor diluted during the accelerated oxidation of 25.20 chromium-nickel steel.

Certain substances as boric acid. silicon and chromium trioxide intensify the corrosivity of vanadium bearing slags.

Calcium oxide and magnesium oxide additions increase the water solubility of variadium bearing slags.

Surface Treatments C and D, as described in the report, substantially reduce the accelerated oxidation potential of vanadium bearing slags and scales.

RECOMMENDATION

It is recommended that consideration be given to trying out the remedial treatments described in this report. The trials should be made by a naval boiler operating agency.

REFERENCES

- (a) EES Rept 040007BL of 30 Dec 1955
- (b) Morosov, A. N. "Investigation of CaO V2O5 System," Metallurg, Vol. 13, No. 12, 1938
- (c) Mellor, J. M. "A Comprehensive Treatise on Inorganic and Theoretical Chemistry," Vol. IX 1933
- (d) EES Rept 04000?AP of 15 Dec 1954
- (e) Buckland, B.O. "Modified Residual Fuel for Gas Turbines,"
 ASME Paper No 54-A-246. Dec 1954